

JET Oscillating Spindle Sander

Model JOSS-S



Machine Purpose: For sanding concave and convex curves.

SAFETY	
-	Must wear safety glasses while operating equipment.
-	Keep hands 2 inches away from revolving drum.
-	Beware of objects that dangle and can get caught in drum/rollers.
-	For best results, KEEP WORKPIECE MOVING AGAINST SPINDLE.
-	This machine has no built-in safety systems.
-	DUST COLLECTION MUST BE TURNED ON.

Spindle Sander	
MATERIAL CAPABILITES	WOOD, ACRYLIC
MINIMUM MATERIAL WIDTH	1/4 INCH
MINIMUM MATERIAL THICKNESS	1/4 INCH
MINIMUM MATERIAL LENGTH	2 INCHES
MAXIMUM MATERIAL WIDTH	N/A
MAXIMUM MATERIAL LENGTH	AMPLE INFEED/OUTFEED CLEARANCE NEEDED.
MATERIAL PREP	
GLUED UP MATERIAL	GLUE MUST BE FULLY DRY (12 HOURS OR MORE) BEFORE RUNNING IT THOUGH. GLUE & GLUE DRIPS MUST BE SCRAPPED OFF MATERIAL BEFORE RUNNING THROUGH.
FINISHED MATERIAL	FINISHES MUST BE FULLY DRIED. MEMBER MUST PROVIDE INFO ON FINISH USED ON MATIERAL.